

## BASIC COMMERCIAL PROPERTY REPORT

### Mississippi State Rating Bureau

6455 Wirtz Rd. Flowood MS 39232 (P)601.981.2915

Property Name: MISSISIPPI STATE RATING BUREAU

Location: 6455 WIRTZ RD FLOWOOD MS 39296

Survey Date: 4 Mar 2022



This Visit is to gather information needed to determine property insurance rates. It is not for property loss prevention or life safety purposes and no life safety or property loss prevention recommendations will be made.



178.06

## BASIC COMMERCIAL PROPERTY

## Mississippi State Rating Bureau

Yanaval				
General				
Company Requesting Report:		Company Contact	•	
MSRB		MSRB		
Account Number:	Policy Number:	Risk Number:		
00	00	610203880		
Field Representative:	Survey Date:	Location Description		
Kevin McWilliams	03/04/2022	MS STATE RATING	BUREAU	
nsured Information				
Income de Manage		۸ ما ما بره م م ب		
Insured Name:  MISSISIPPI STATE RATING BUREAU		Address: 6455 WIRTZ RD		
MISSISII I I STATE NATING BONEAU		0433 WITTE ITE		
City / District:		Zip Code:	County:	
		39296	Rankin	
Phone Number: La	titude:	Longitude:	The Insure	ad is the:
	2.34998	-90.02808	Owner	su is tile.
001 001 2010		30.02000	OWNE	
Conferred With:	Title:	Neighborhood Type:	Trend:	Occupancy:
JOE SHUMAKER	MANAGER	Mixed	Stable	Single
List of Occupants:				
		Describe		Position on Harris
Occupancy		Describe		Business Hours
MISSISSIPPI STATE RATING	BUREAU	OFFICE		MON_FDI_ Q:00 A M TO 5:30
MWUA		OFFICE		MON_FDI_ Q:00 A M TO 5:30
MRPIUA		OFFICE		MON-EDI- 8.00 V M TO 2.30
uilding Information				
	Desiles Charings		La como de Amor	Nananah Amana 2
	Built: Stories:	Ground Floor: Total Area		
4303 0702 2013	ONE	16,988	16,988	No
Type of Construction:  - Steel Frame w/Metal Studs		Wall Flnish:		Il Condition:
- Steel Frame Wivietal Studs	- Brick \	/eneer	Go	<u>ou</u>
Construction Class:				
% 1 - Frame % 2 - Joisted	Masonry 100 % 3 - Non-Co	ombustible		% 6 - Fire Resistive
Floor Construction:	Roof Ma			undation Type:
- Concrete	- Memb	rane - EPDM or PVC	Slal	b / Grade
Roof Deck:	Roof Fra	ame Type:	Roc	of Geometry:
- Metal Deck	- Steel E	Bar Joists	Flat	t
Doof Conditions	11		Facility Nacday	
Roof Condition: Upkeep: Good Good	Use: Office		Facility Needs: None	
Guu	Office		INOLIC	
MWUA Zone:	Flood Zone:	Sprinkler Type:	Alar	rm Type:
	Not in High Hazard Flood Zo			ntral
Cost per Square Ft. :	Total Replacement Cost:	Estimated Replacement Cost is o	lerived using 360 Value traden	mark software. Costs represent general estimates

3,024,963.21

which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that

are common to the types of structures represented in the software.



## BASIC COMMERCIAL PROPERTY

### Mississippi State Rating Bureau

Exposures						
Any Structural Exposures within 200 ft. ? Yes	External exposures other than normal? No					
Any evidence of damage caused by natural No hazards or vandalism?	Is any part of the building used for residential dwelling? No					

#### List of Exposures

Direction	Distance (ft)	Height (Stories)	Construction	Occupancy
Left	133	ONE	Non-Combustible	OFFICE

Fire Protection							
Public Protection	n Class: 3RD	Class at Risk: 3RD	Is the Risk located inside a city?	Yes			
Is there a Hydra	nt within 1000'?	es					
Primary Responding Fire Department: FLOWOOD							
Under 5 miles to Fire Dept? Yes Type of Fire Dept: Paid							
Is the risk equip	ped with fire extinguis	hers? Yes	Automatic fire sprinkler system?	Yes			
Alarm System:	Both	Is there any commercial cooking	g? No				
Specify:	Central						

#### **Comments**

Lit exit signs are installed at each exit.

Fire pull stations are installed at each entrance and exit.

Fire extinguishers are well located and tagged.

Fire strobe lights are installed in the hallways and on the interior walls.

There is one smoke detector located in the server room.

There are 10 air units located on the roof.

Cameras are installed at each entrance, exit, and break room.

Cameras are installed outside the building as well.

Residential type electric stove and two microwaves in use.

The stove is protected by a Guardian 3 Model G 300-B extinguishing system,

and is inspected every 6 months.

All exterior doors except the front are locked, entrance by security code only.


There is one storm drain 110 feet to the east and one drainage ditch 54 feet to the west of the building.

The building has a 150 KW natural gas back-up generator installed, and is automatically tested weekly.



# BASIC COMMERCIAL PROPERTY REPORT Mississippi State Rating Bureau

Picture 1



Picture 2

Front Photo





## BASIC COMMERCIAL PROPERTY REPORT

Mississippi State Rating Bureau

Picture 3

Rear Photo



Picture 4

Roof





# BASIC COMMERCIAL PROPERTY REPORT Mississippi State Rating Bureau

Picture 5

Roof & Screened Area for air units



Picture 6 Air units on roof

